

Work Order ID 76201

76201

Page 1

November-07-11 2:36:05 PM

Item ID: D3161-3 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Hinge 15.0"
 Start Date: 07/11/2011 Start Qty: 4.00 ***4*** Cust Item ID:
 Required Date: 21/11/2011 Req'd Qty: 4.00 ***4*** Customer:

Reference:

Approvals: Process Plan: M.L.O Date: 11/11/10 Tooling: _____ Date: _____
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***
 Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3161	Rev A2

100 ***100*** Small Fab 0.00
 Small Fab Memo 0.00
 Small Fab Cut to length as per dwg (15.0" long) and punch end of hinge close. Debur if necessary

110 ***110*** QC5- Inspect part completeness to step on W/O 0.00
 QC Memo 0.00
 Quality Control

120 ***120*** Identify as per dwg & Stock Location: 37 0.00
 Packaging Memo 0.00
 Packaging

EB 11/11/30 (8)

11 11 30 (8)

11/11/30 (80) P

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 76201

76201

Page 2

November-07-11 2:36:05 PM

Item ID: D3161-3 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Hinge 15.0"
 Start Date: 07/11/2011 Start Qty: 4.00 ***4*** Cust Item ID:
 Required Date: 21/11/2011 Req'd Qty: 4.00 ***4*** Customer:
 Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	QC21- Final Inspection - Work Order Release	0.00							
130									
QC	Memo	0.00							
Quality Control									

U 11.11.30

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

November-07-11 2:36:09 PM

Page 1

Work Order ID: 76201

76201

Parent Item: D3161-3

D3161-3

Parent Item Name: Hinge 15.0"

Start Date: 07/11/2011

Required Date: 21/11/2011

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP A02.04.26New IssueNG
IPP Rev:B 08-04-29 update seq. 1 DD verified by:ec

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

MS20257-3-7200

Purchased

No

100

f

2.5764

1.44

6.063158

MS20257-3-7200

**

Piano Hinge

Location

Loc Qty

Loc Code

ST449

0.00778948

116817

0.00778948

ST489A

2.56864

117543

2.126

118686

0.44264

M119638 = 11.52
~~6.063158~~

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN #	DRAWN BY #	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED KF	APPROVED #	DRAWING NO. D3161	REV. A SHEET 1 OF 1
DATE 02.04.24		TITLE HINGE	SCALE NTS
A	02.04.24	NEW ISSUE	
A1	04.02.27	ADDED D3161-5	
A2	04.06.30	ADD D3161-7 & D3161-9	

RELEASED
02.04.24 #

P/N	LENGTH 'L'	DESCRIPTION
D3161-1	13.5"	HINGE (REPLACES MS20257-3-135 ON D2183)
D3161-3	15.0"	HINGE (REPLACES MS20257-3-150 ON D2950-041)
D3161-5	9.9"	HINGE
D3161-7	14.0"	HINGE
D3161-9	17.0"	HINGE



NOTES:

- ① MAKE FROM MS20257-3-7200 HINGE

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 76201

11-11-08

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.